

Safety Issue Type: Recalls

December 01 2021 NHTSA Campaign Number: 21C005000

Loose Foam in Child Seat May Become Choking Hazard

Loose pieces of foam can present a choking hazard to a child, increasing the risk of injury.

NHTSA Campaign Number 21C005000

Manufacturer Clek, Inc.

Components CHILD SEAT

Potential Number of Units Affected 150599

Summary

Clek, Inc. (Clek) is recalling certain Foof, model numbers FO12 through FO19, and Fllo, model numbers FL15 through FL19, convertible child seats manufactured prior to May 21, 2021. A child may pick pieces of foam from the foam cushion located under the seat pad.

Remedy

Clek will provide a molded plastic insert that prevents access to the foam, along with instructions on how to attach it to the child seat, free of charge. Owner notification letters are expected to be mailed in December 2021. Owners may contact Clek customer service at 1-866-656-2462.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Affected Products (2)

Child Seat

CLEK	FLLO	9999
CLEK	FOONF	9999

Associated Documents (6)

Remedy Instructions and TSB

RCRIT-21C005-0139.pdf 726.369KB

<https://static.nhtsa.gov/odi/rcl/2021/RCRIT-21C005-0139.pdf>

Recall 573 Report - Amendment 2

RCLRPT-21C005-4812.PDF 217.046KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21C005-4812.PDF>

Defect Notice 573 Report

RCLRPT-21C005-3520.PDF 217.1KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21C005-3520.PDF>

Recall 573 Report - Amendment 3

RCLRPT-21C005-4948.PDF 218.544KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21C005-4948.PDF>

Recall Acknowledgement

RCAK-21C005-1232.pdf 781.415KB

<https://static.nhtsa.gov/odi/rcl/2021/RCAK-21C005-1232.pdf>

Recall 573 Report - Amendment 1

RCLRPT-21C005-1869.PDF 217.107KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21C005-1869.PDF>