

## Safety Issue Type: Recalls

**December 20 2021** NHTSA Campaign Number: 21C007000

### Label Can Come Apart and May Pose Choking Hazard

Detached pieces of the labels can present a choking hazard to a child, increasing the risk of injury.

NHTSA Campaign Number 21C007000

Manufacturer Clek, Inc.

Components EQUIPMENT, CHILD SEAT

Potential Number of Units Affected 596

#### Summary

Clek, Inc. (Clek) is recalling certain Liing, model LG19U1, and Liingo, model number LGO20U1, infant child seats manufactured before February 22, 2021. The labels on the seat cover or infant insert may bubble up, allowing the labels to come apart into small pieces.

#### Remedy

Clek will provide a replacement seat cover or infant insert, free of charge. Owner notification letters are expected to be mailed in January 2022. Owners may contact Clek customer service at 1-866-656-2462.

#### Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).

## Affected Products (2)

### Child Seat

CLEK	LIING	9999
CLEK	LIINGO	9999

## Associated Documents (4)

Recall 573 Report - Amendment 1

RCLRPT-21C007-4898.PDF 218.577KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21C007-4898.PDF>

Recall 573 Report - Amendment 1

RCLRPT-21C007-5563.PDF 218.577KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21C007-5563.PDF>

Defect Notice 573 Report

RCLRPT-21C007-6953.PDF 218.573KB

<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21C007-6953.PDF>

Recall Acknowledgement

RCAK-21C007-5472.pdf 830.844KB

<https://static.nhtsa.gov/odi/rcl/2021/RCAK-21C007-5472.pdf>